

Physical World and Measurement – Formula Sheet

- Dimensional formula: $[M^a L^b T^c]$
- Least count = Value of 1 MSD – Value of 1 VSD
- Percentage error = $(\Delta A / A) \times 100$
- Relative error = $\Delta A / A$
- Dimensional consistency: LHS = RHS